
## 10 REASONS TO CHANGE TO

## NEAR DRY MACHINIC

(COOLANT FREE MACHINING)



- 1 Eliminates flood coolant systems.
- 2 Eliminates coolant disposal costs.
- 3 Improved tool life.
- 4 Produces dry chips.
- 5 Safe working environment (no spillages).
- 6 No recirculation of old fluids.
- The Eliminates skin disorders such as dermatitis.
- 8 Reduced fluid costs.
- 9 Improved surface finish.
- 10 An environmentally clean green and safe solution.

## LIFE TIME WARRANTY



Unist Australia Pty Ltd

7 Bendtree Way, Castle Hill NSW 2154

www.unist.com.au

PH: (02) 8850 2022 FAX: (02) 8850 2033 MOB: 0418 274 946 Email: johnbarker@unist.com.au